BUILDING SAFETY CERTIFICATE

NO 1445/ Safty Correll	No. ;-	1443/	Safty	condificate
------------------------	--------	-------	-------	-------------

Dated: 23-03. 214

It is certified that the existing building ST. Anthony's School at Vill Rahrai, Post Rahra Distt. Amroha is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	03 No. Ground Floor First Floor Second Floor	-	100	-		

The building is owned/occupied by. ST. Anthony's School have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PWD on 20-06-2024 (date of inspection) in the presence of Mr. Roy Mathews and that the building/premises is fit for occupancy for running school with effect from. 20-06-2024 for a period of 01 Years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1. Continuous Monthy maintenance of building during above period.
- 2. Continuous Cleaning of rain water pipes and roof & top before rains.
- 3. During above Period if any cracks seen in building, information to be given to department for further inspection for instruction.

Issued on :-

Signature with Seal:

प्रान्तीय खण्ड, लो०नि०वि० अमरोहा

Name:

Baljeet Singh Saharan Assistant Engineer

Designation : Name add Address

Provincial Division P.W.D.

of Department/office -Amroha

Note- The certificate should be signed/Issued by Assistant Engineer and above officer of concerned Govt. Department only.

THE MANAGER
ST ANTHONY'S SCHOOL
VIIL. Rahral, Post- Rahva
Diett. Amrohafu. P

THE PRINCIPAL
STANTHONY'S SCHOOL
Vill - Rahrai Post Rahra
Distt Amroha (UP)